

Facility Summary in Sheridan County in the City of Medicine Lake

Location: LAKE PIT STOP
729 Main St
Medicine Lake, MT 59247 Sheridan

System Facility ID:46-01127

Facility Code: 27958
Last Inspected On: 10/28/2021
Operating Permit Renewal Date: 03/30/2025

Note: Inspection is due 90 days before the Operating Permit Renewal Date.

Owner Operator Contact: Lake Pit Stop LLC 4067892242

Operator Contact: Chanel Johnson;James BoBo;Robert Herman 4064805957;7015722478

Owner/Operator: Lake Pit Stop LLC

Chanel Johnson, UST Class A Operator
Chanel Johnson, UST Class B Operator
James BoBo, UST Class A Operator
James BoBo, UST Class B Operator
Robert Herman, UST Class A Operator

Tank Code	S6	Tank Age	25	Tank Installed Date	10/01/1997	Tank Material	Unknown	Piping Material	Flexible Plastic	Overfill Types	
Tag Number	2323	Spill Test Date		Piping Installed Date	06/03/2013	Tank Construction		Piping Construction	Double Walled	AST	Yes
Tank Status	Currently in Use	MLLD Test Date	12/15/2021	Sump Tightness Test Date	10/28/2021	Catastrophic L.D Type 3.0	Continuous Interstitial Monitoring;Mechanical Line Leak Detector	Piping Type	Pressurized	CP Met Types	
Product	Gasoline	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection	Deferred	Primary Pipe Detection	Continuous Interstitial Monitoring	Vapor Recovery	No
Capacity	15000	ATG Test Date		Line Tightness Test Date	04/24/2015	Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	Yes
		Overfill Test Date				ATG Type	Vaporless Manufacturing/Vaporless 99LD-2000				
Tank Code	S7	Tank Age	25	Tank Installed Date	10/01/1997	Tank Material	Unknown	Piping Material	Flexible Plastic	Overfill Types	
Tag Number	2324	Spill Test Date		Piping Installed Date	06/03/2013	Tank Construction		Piping Construction	Double Walled	AST	Yes

Tank Status	Currently in Use	MLLD Test Date	12/15/2021	Sump Tightness Test Date	10/28/2021	Catastrophic L.D Type 3.0	Continuous Interstitial Monitoring;Mechanical Line Leak Detector	Piping Type	Pressurized	CP Met Types	
Product	Diesel	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection	Deferred	Primary Pipe Detection	Continuous Interstitial Monitoring	Vapor Recovery	No
Capacity	12000	ATG Test Date		Line Tightness Test Date	04/24/2015	Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	Yes
		Overfill Test Date				ATG Type	Vaporless Manufacturing/Vaporless 99LD-2000				
Tank Code	S8	Tank Age	25	Tank Installed Date	10/01/1997	Tank Material	Unknown	Piping Material	Flexible Plastic	Overfill Types	
Tag Number	2325	Spill Test Date		Piping Installed Date	06/03/2013	Tank Construction		Piping Construction	Double Walled	AST	Yes
Tank Status	Currently in Use	MLLD Test Date	12/15/2021	Sump Tightness Test Date	10/28/2021	Catastrophic L.D Type 3.0	Continuous Interstitial Monitoring;Mechanical Line Leak Detector	Piping Type	Pressurized	CP Met Types	
Product	Diesel	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection	Deferred	Primary Pipe Detection	Continuous Interstitial Monitoring	Vapor Recovery	No
Capacity	12000	ATG Test Date		Line Tightness Test Date	04/24/2015	Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	Yes
		Overfill Test Date				ATG Type	Vaporless Manufacturing/Vaporless 99LD-2000				
Tank Code	S9	Tank Age	25	Tank Installed Date	10/01/1997	Tank Material	Unknown	Piping Material	Flexible Plastic	Overfill Types	
Tag Number	2326	Spill Test Date		Piping Installed Date	06/03/2013	Tank Construction		Piping Construction	Double Walled	AST	Yes
Tank Status	Currently in Use	MLLD Test Date	12/15/2021	Sump Tightness Test Date	10/28/2021	Catastrophic L.D Type 3.0	Continuous Interstitial Monitoring;Mechanical Line Leak Detector	Piping Type	Pressurized	CP Met Types	
Product	Gasoline	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection	Deferred	Primary Pipe Detection	Continuous Interstitial Monitoring	Vapor Recovery	No
Capacity	8000	ATG Test Date		Line Tightness Test Date	04/24/2015	Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	Yes
		Overfill Test Date				ATG Type	Vaporless Manufacturing/Vaporless 99LD-2000				

Facility Summary in Sheridan County in the City of Medicine Lake

Location: MEDICINE LAKE SCHOOL DIST 7
1 Young St
Medicine Lake, MT 59247 Sheridan

System Facility ID:46-01122

Facility Code: 27957
Last Inspected On: 04/20/2022
Operating Permit Renewal Date: 06/03/2025

Note: Inspection is due 90 days before the Operating Permit Renewal Date.

Owner Operator Contact:	School Dist 7 Medicine Lake	4067892211
Operator Contact:	Aaron Webster	4067892211

Owner/Operator: School Dist 7 Medicine Lake

Aaron Webster, UST Class A Operator
Aaron Webster, UST Class B Global Operator
Sandor Forizs, UST Class B Operator

Tank Code	S3	Tank Age	31	Tank Installed Date	08/01/1991	Tank Material	Steel Clad	Piping Material	Flexible Plastic	Overfill Types	Flapper Valve
Tag Number	1603	Spill Test Date	06/14/2022	Piping Installed Date		Tank Construction	Double-Walled	Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date	04/26/2019	Catastrophic L.D Type 3.0	Auto Dialer	Piping Type	U.S. Suction	CP Met Types	Non-corrodible
Product	Heating Oil	PLLD Test Date		Tank/Piping CP Test Date	01/16/2014	Primary Tank Leak Detection	Continuous Interstitial Monitoring	Primary Pipe Detection	3-Year Line Tightness Test	Vapor Recovery	No
Capacity	10066	ATG Test Date	04/20/2022	Line Tightness Test Date	04/20/2022	Secondary Tank Leak Detection		Secondary Pipe Detection	Continuous Interstitial Monitoring	Energy Act	No
		Overfill Test Date	06/14/2022			ATG Type	OPW / EMCO/EECO 1500				

Facility Summary in Sheridan County in the City of Plentywood

Location: AUTO TECH SERVICES
327 W 1st Ave
Plentywood, MT 59254-1802 Sheridan

System Facility ID:46-01524

Facility Code: 27977
Last Inspected On: 04/21/2022
Operating Permit Renewal Date: 04/21/2025

Note: Inspection is due 90 days before the Operating Permit Renewal Date.

Owner Operator Contact:	Farmers Union Oil Co Plentywood
-------------------------	---------------------------------

Owner/Operator: Farmers Union Oil Co Plentywood

James Kibbe, UST Class A Operator
James Kibbe, UST Class B Global Operator
L James Kibbe, UST Class A Operator
L James Kibbe, UST Class B Global Operator

Tank Code	08	Tank Age	33	Tank Installed Date	12/10/1989	Tank Material	Cathodically Protected Steel	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	High Level Alarm
Tag Number	1114	Spill Test Date		Piping Installed Date		Tank Construction		Piping Construction	None	AST	No
Tank Status	Temporarily Out of Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Not Required	Piping Type	Safe Suction	CP Met Types	Galvanic
Product	Diesel	PLLD Test Date		Tank/Piping CP Test Date	04/21/2022	Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection		Vapor Recovery	No
Capacity	4000	ATG Test Date		Line Tightness Test Date		Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		Overfill Test Date				ATG Type	Veeder Root/TLS-450				
Tank Code	09	Tank Age	33	Tank Installed Date	12/10/1989	Tank Material	Cathodically Protected Steel	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	High Level Alarm
Tag Number	1115	Spill Test Date		Piping Installed Date		Tank Construction		Piping Construction	None	AST	No
Tank Status	Temporarily Out of Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Not Required	Piping Type	Safe Suction	CP Met Types	Galvanic
Product	Gasoline	PLLD Test Date		Tank/Piping CP Test Date	04/21/2022	Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection		Vapor Recovery	No
Capacity	4000	ATG Test Date		Line Tightness Test Date		Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		Overfill Test Date				ATG Type	Veeder Root/TLS-450				
Tank Code	10	Tank Age	33	Tank Installed Date	12/10/1989	Tank Material	Cathodically Protected Steel	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	High Level Alarm
Tag Number	1116	Spill Test Date		Piping Installed Date		Tank Construction		Piping Construction	None	AST	No
Tank Status	Temporarily Out of Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Not Required	Piping Type	Safe Suction	CP Met Types	Galvanic
Product	Gasoline	PLLD Test Date		Tank/Piping CP Test Date	04/21/2022	Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection		Vapor Recovery	No
Capacity	10000	ATG Test Date		Line Tightness Test Date		Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		Overfill Test Date				ATG Type	Veeder Root/TLS-450				

Facility Summary in Sheridan County in the City of Plentywood

Location: FARMERS UNION OIL CO PLENTYWOOD
301 W 1st Ave
Plentywood, MT 59254-1802 Sheridan

System Facility ID:46-06801

Facility Code: 28147
Last Inspected On: 08/04/2021
Operating Permit Renewal Date: 08/23/2024

Note: Inspection is due 90 days before the Operating Permit Renewal Date.

Owner Operator Contact: Farmers Union Oil Co Plentywood
Operator Contact: L Kibbe

Owner/Operator: Farmers Union Oil Co Plentywood

L James Kibbe, UST Class A Operator
L James Kibbe, UST Class B Global Operator

Tank Code	09	Tank Age	26	Tank Installed Date	06/01/1996	Tank Material	Cathodically Protected Steel	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	Flapper Valve
Tag Number	1038	Spill Test Date		Piping Installed Date		Tank Construction		Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date	06/13/2015	Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Galvanic
Product	Gasoline	PLLD Test Date	06/18/2021	Tank/Piping CP Test Date	06/17/2021	Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	ELLD 0.2	Vapor Recovery	No
Capacity	20000	ATG Test Date		Line Tightness Test Date	07/28/2016	Secondary Tank Leak Detection		Secondary Pipe Detection	Continuous Interstitial Monitoring	Energy Act	No
		Overfill Test Date				ATG Type	Veeder Root/TLS-450				
Tank Code	10	Tank Age	26	Tank Installed Date	06/01/1996	Tank Material	Cathodically Protected Steel	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	Flapper Valve
Tag Number	1039	Spill Test Date		Piping Installed Date	05/20/2009	Tank Construction		Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date	06/13/2015	Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Galvanic
Product	Diesel	PLLD Test Date	06/18/2021	Tank/Piping CP Test Date	06/17/2021	Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	ELLD 0.2	Vapor Recovery	No
Capacity	20000	ATG Test Date		Line Tightness Test Date	07/28/2016	Secondary Tank Leak Detection		Secondary Pipe Detection	Continuous Interstitial Monitoring	Energy Act	No
		Overfill Test Date				ATG Type	Veeder Root/TLS-450				
Tank Code	11	Tank Age	26	Tank Installed Date	06/01/1996	Tank Material	Cathodically Protected Steel	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	Flapper Valve

Tag Number	1040	Spill Test Date		Piping Installed Date		Tank Construction		Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date	06/13/2015	Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Galvanic
Product	Gasoline	PLLD Test Date	06/18/2021	Tank/Piping CP Test Date	06/17/2021	Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	ELLD 0.2	Vapor Recovery	No
Capacity	12000	ATG Test Date		Line Tightness Test Date	07/28/2016	Secondary Tank Leak Detection		Secondary Pipe Detection	Continuous Interstitial Monitoring	Energy Act	No
		Overfill Test Date				ATG Type	Veeder Root/TLS-450				
Tank Code	12	Tank Age	26	Tank Installed Date	06/01/1996	Tank Material	Cathodically Protected Steel	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	Flapper Valve
Tag Number	1041	Spill Test Date		Piping Installed Date		Tank Construction		Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date	06/13/2015	Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Galvanic
Product	Diesel	PLLD Test Date	06/18/2021	Tank/Piping CP Test Date	06/17/2021	Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	ELLD 0.2	Vapor Recovery	No
Capacity	12000	ATG Test Date		Line Tightness Test Date	03/24/2016	Secondary Tank Leak Detection		Secondary Pipe Detection	Continuous Interstitial Monitoring	Energy Act	No
		Overfill Test Date				ATG Type	Veeder Root/TLS-450				
Tank Code	13	Tank Age	26	Tank Installed Date	06/01/1996	Tank Material	Cathodically Protected Steel	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	Flapper Valve
Tag Number	1042	Spill Test Date		Piping Installed Date		Tank Construction		Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date	06/13/2015	Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Galvanic
Product	Diesel	PLLD Test Date	06/18/2021	Tank/Piping CP Test Date	06/17/2021	Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	ELLD 0.2	Vapor Recovery	No
Capacity	12000	ATG Test Date		Line Tightness Test Date	07/28/2016	Secondary Tank Leak Detection		Secondary Pipe Detection	Continuous Interstitial Monitoring	Energy Act	No
		Overfill Test Date				ATG Type	Veeder Root/TLS-450				
Tank Code	14	Tank Age	26	Tank Installed Date	06/01/1996	Tank Material	Cathodically Protected Steel	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	Flapper Valve
Tag Number	1043	Spill Test Date		Piping Installed Date		Tank Construction		Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date	06/13/2015	Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Galvanic
Product	Diesel	PLLD Test Date	06/18/2021	Tank/Piping CP Test Date	06/17/2021	Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	ELLD 0.2	Vapor Recovery	No

Capacity	8000	ATG Test Date		Line Tightness Test Date	03/24/2016	Secondary Tank Leak Detection		Secondary Pipe Detection	Continuous Interstitial Monitoring	Energy Act	No
		Overfill Test Date				ATG Type	Veeder Root/TLS-450				
Tank Code	15	Tank Age	26	Tank Installed Date	06/01/1996	Tank Material	Cathodically Protected Steel	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	Flapper Valve
Tag Number	1044	Spill Test Date		Piping Installed Date		Tank Construction		Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date	06/13/2015	Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Galvanic
Product	Diesel	PLLD Test Date	06/18/2021	Tank/Piping CP Test Date	06/17/2021	Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	ELLD 0.2	Vapor Recovery	No
Capacity	8000	ATG Test Date		Line Tightness Test Date	03/24/2016	Secondary Tank Leak Detection		Secondary Pipe Detection	Continuous Interstitial Monitoring	Energy Act	No
		Overfill Test Date				ATG Type	Veeder Root/TLS-450				

Facility Summary in Sheridan County in the City of Plentywood

Location: KUM AND GO STORE 808
211 W 1st Ave
Plentywood, MT 59254-1830 Sheridan

System Facility ID:46-05200

Facility Code: 28101
Last Inspected On: 04/08/2020
Operating Permit Renewal Date: 09/10/2023

Note: Inspection is due 90 days before the Operating Permit Renewal Date.

Owner Operator Contact: Krause Gentle Corp5152260128

Operator Contact: Amanda Schumacher;Anthony Alred;Christopher Bergman;Kevin Kautzman;Mike Simpson;Wayne Lundquist4805886181;7013401435;7013918114;7016094711;7632293142;9522003139

Owner/Operator: Krause Gentle Corp

- Aeon Long, UST Class B Global Operator
- Amanda Schumacher, UST Class A Operator
- Amanda Schumacher, UST Class B Global Operator
- Anthony Alred, UST Class A Operator
- Anthony Alred, UST Class B Global Operator
- Christopher Bergman, UST Class A Operator
- Kevin Kautzman, UST Class A Operator
- Kevin Kautzman, UST Class B Global Operator
- Mike Simpson, UST Class A Operator
- Wayne Lundquist, UST Class A Operator
- Wayne Lundquist, UST Class B Global Operator

Tank Code	03	Tank Age	40	Tank Installed Date	12/01/1982	Tank Material	Cathodically Protected Steel	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	Flapper Valve
Tag Number	1498	Spill Test Date		Piping Installed Date	06/26/2009	Tank Construction	Lined Interior/Impressed Current	Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Impressed Current
Product	Diesel	PLLD Test Date		Tank/Piping CP Test Date	04/08/2020	Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	ELLD 0.2	Vapor Recovery	No
Capacity	6000	ATG Test Date		Line Tightness Test Date	08/28/2014	Secondary Tank Leak Detection		Secondary Pipe Detection	Continuous Interstitial Monitoring	Energy Act	No
		Overfill Test Date				ATG Type	Gilbarco-Veeder Root/TLS-350/Gilbarco EMC;Veeder Root/8484 Series PLLD				
Tank Code	05	Tank Age	34	Tank Installed Date	01/01/1988	Tank Material	Bare Steel	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	Flapper Valve
Tag Number	1500	Spill Test Date		Piping Installed Date	06/26/2009	Tank Construction		Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Impressed Current
Product	Gasoline	PLLD Test Date		Tank/Piping CP Test Date	04/08/2020	Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	ELLD 0.2	Vapor Recovery	No
Capacity	12000	ATG Test Date		Line Tightness Test Date	08/28/2014	Secondary Tank Leak Detection		Secondary Pipe Detection	Continuous Interstitial Monitoring	Energy Act	No
		Overfill Test Date				ATG Type	Gilbarco-Veeder Root/TLS-350/Gilbarco EMC;Veeder Root/8484 Series PLLD				
Tank Code	04	Tank Age	34	Tank Installed Date	01/01/1988	Tank Material	Bare Steel	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	Flapper Valve
Tag Number	4358	Spill Test Date		Piping Installed Date	06/26/2009	Tank Construction		Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Impressed Current
Product	Gasoline	PLLD Test Date		Tank/Piping CP Test Date	04/08/2020	Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	ELLD 0.2	Vapor Recovery	No
Capacity	12000	ATG Test Date		Line Tightness Test Date	08/28/2014	Secondary Tank Leak Detection		Secondary Pipe Detection	Continuous Interstitial Monitoring	Energy Act	No

		Overfill Test Date				ATG Type	Gilbarco-Veeder Root/TLS- 350/Gilbarco EMC;Veeder Root/8484 Series PLLD				
--	--	--------------------	--	--	--	----------	--	--	--	--	--

Facility Summary in Sheridan County in the City of Plentywood

Location:	MILLER OIL CO INC E RAILROAD AVE 416 W Railroad Ave Plentywood, MT 59254 Sheridan	System Facility ID:	46-08609	Facility Code:	28240	Last Inspected On:	10/28/2021	Operating Permit Renewal Date:	03/04/2025
-----------	---	---------------------	----------	----------------	-------	--------------------	------------	--------------------------------	------------

Note: Inspection is due 90 days before the Operating Permit Renewal Date.

Owner Operator Contact:	Miller Oil Co Inc Culbertson
-------------------------	------------------------------

Operator Contact:	Kevin Miller;Matthew Miller	4067657730
-------------------	-----------------------------	------------

Owner/Operator: Miller Oil Co Inc Culbertson

Kevin Miller, UST Class A Operator
Kevin Miller, UST Class B Operator
Matthew Miller, UST Class A Operator
Matthew Miller, UST Class B Global Operator

Tank Code	S1	Tank Age	55	Tank Installed Date	04/08/1967	Tank Material	Bare Steel	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	
Tag Number	1617	Spill Test Date		Piping Installed Date	03/23/2009	Tank Construction		Piping Construction	Double Walled	AST	Yes
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date	06/18/2015	Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	
Product	Gasoline	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection		Primary Pipe Detection	ELLD 0.2	Vapor Recovery	No
Capacity	12048	ATG Test Date		Line Tightness Test Date	08/05/2009	Secondary Tank Leak Detection		Secondary Pipe Detection	Continuous Interstitial Monitoring	Energy Act	No
		Overfill Test Date				ATG Type	Franklin Fueling Systems/TS-LLD				
Tank Code	S2	Tank Age	61	Tank Installed Date	04/07/1961	Tank Material	Bare Steel	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	
Tag Number	1618	Spill Test Date		Piping Installed Date	03/23/2009	Tank Construction		Piping Construction	Double Walled	AST	Yes
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date	06/18/2015	Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	

Product	Diesel	PLLD Test Date		Tank/Piping CP Test Date	08/08/2006	Primary Tank Leak Detection		Primary Pipe Detection	ELLD 0.2	Vapor Recovery	No
Capacity	5327	ATG Test Date		Line Tightness Test Date	08/05/2009	Secondary Tank Leak Detection		Secondary Pipe Detection	Continuous Interstitial Monitoring	Energy Act	No
		Overfill Test Date				ATG Type	Franklin Fueling Systems/TS-LLD				
Tank Code	S3	Tank Age	55	Tank Installed Date	04/08/1967	Tank Material	Bare Steel	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	
Tag Number	1619	Spill Test Date		Piping Installed Date	03/23/2009	Tank Construction		Piping Construction	Double Walled	AST	Yes
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date	06/18/2015	Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	
Product	Diesel	PLLD Test Date		Tank/Piping CP Test Date	08/08/2006	Primary Tank Leak Detection		Primary Pipe Detection	ELLD 0.2	Vapor Recovery	No
Capacity	14848	ATG Test Date		Line Tightness Test Date	08/05/2009	Secondary Tank Leak Detection		Secondary Pipe Detection	Continuous Interstitial Monitoring	Energy Act	No
		Overfill Test Date				ATG Type	Franklin Fueling Systems/TS-LLD				
Tank Code	S4	Tank Age	54	Tank Installed Date	04/07/1968	Tank Material	Bare Steel	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	
Tag Number	1620	Spill Test Date		Piping Installed Date	03/23/2009	Tank Construction		Piping Construction	Double Walled	AST	Yes
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date	06/18/2015	Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	
Product	Diesel	PLLD Test Date		Tank/Piping CP Test Date	08/08/2006	Primary Tank Leak Detection		Primary Pipe Detection	ELLD 0.2	Vapor Recovery	No
Capacity	14773	ATG Test Date		Line Tightness Test Date	08/05/2009	Secondary Tank Leak Detection		Secondary Pipe Detection	Continuous Interstitial Monitoring	Energy Act	No
		Overfill Test Date				ATG Type	Franklin Fueling Systems/TS-LLD				

Facility Summary in Sheridan County in the City of Plentywood

Location:	MONTANA PIONEER MANOR INC 605 Sheridan St Plentywood, MT 59254-1715 Sheridan	Facility Code:	28282
		Last Inspected On:	03/07/2022
	System Facility ID:46-10679	Operating Permit Renewal Date:	06/04/2025
Note: Inspection is due 90 days before the Operating Permit Renewal Date.			

Owner Operator Contact: Montana Pioneer Manor Inc4067651362

Operator Contact: Robert Manley

Owner/Operator: Montana Pioneer Manor Inc

Robert Manley, UST Class A Operator
Robert Manley, UST Class B Global Operator

Tank Code	S2	Tank Age	26	Tank Installed Date	05/01/1996	Tank Material	Steel Clad	Piping Material	Flexible Plastic	Overfill Types	Flapper Valve
Tag Number	1673	Spill Test Date	04/20/2022	Piping Installed Date		Tank Construction	Double-Walled	Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date	01/23/2019	Catastrophic L.D Type 3.0	Not Required	Piping Type	U.S. Suction	CP Met Types	Non-corrodible
Product	Heating Oil	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection	Manual Interstitial Monitoring	Primary Pipe Detection	3-Year Line Tightness Test	Vapor Recovery	No
Capacity	10000	ATG Test Date		Line Tightness Test Date	04/07/2022	Secondary Tank Leak Detection		Secondary Pipe Detection	Manual Interstitial Monitoring	Energy Act	No
		Overfill Test Date	04/20/2022			ATG Type					

Facility Summary in Sheridan County in the City of Plentywood

Location: SHERIDAN COUNTY
100 W Laurel Ave
Plentywood, MT 59254-1647 Sheridan

Facility Code: 28126
Last Inspected On: 02/10/2020
System Facility ID:46-06278
Operating Permit Renewal Date: 06/18/2023

Note: Inspection is due 90 days before the Operating Permit Renewal Date.

Owner Operator Contact: Sheridan County Sanitarian 4067652310

Operator Contact: Arthur Kurk;Austin Tommerup;D. A. Michels;Gary Bartnes;Jerry Hendrickson;Monica Vines;Ricky Lagerquist 4064892017;4067652310;4067657046;4067657702;4069393719

Owner/Operator: Sheridan County Sanitarian

Arthur Kurk, UST Class A Operator
Austin Tommerup, UST Class A Operator
D. A. Michels, UST Class A Operator
Gary Bartnes, UST Class A Operator
Gary Bartnes, UST Class B Global Operator
Jerry Hendrickson, UST Class A Operator
Jody Lowe, UST Class B Operator
Monica Vines, UST Class A Operator
Ricky Lagerquist, UST Class A Operator
Ryan Mitchell, UST Class B Operator

Tank Code	S2	Tank Age	27	Tank Installed Date	09/01/1995	Tank Material	Steel Clad	Piping Material	Flexible Plastic	Overfill Types	Flapper Valve
-----------	----	----------	----	---------------------	------------	---------------	------------	-----------------	------------------	----------------	---------------

Product	Diesel	PLLD Test Date		Tank/Piping CP Test Date	01/05/2011	Primary Tank Leak Detection	Manual Interstitial Monitoring	Primary Pipe Detection		Vapor Recovery	No
Capacity	10150	ATG Test Date		Line Tightness Test Date		Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		Overfill Test Date				ATG Type					
Tank Code	07	Tank Age	32	Tank Installed Date	01/01/1990	Tank Material	Steel Clad	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	Flapper Valve
Tag Number	1914	Spill Test Date		Piping Installed Date		Tank Construction	Double-Walled	Piping Construction	None	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Not Required	Piping Type	Safe Suction	CP Met Types	Non-corrodible
Product	Diesel	PLLD Test Date		Tank/Piping CP Test Date	01/05/2011	Primary Tank Leak Detection	Manual Interstitial Monitoring	Primary Pipe Detection		Vapor Recovery	No
Capacity	10150	ATG Test Date		Line Tightness Test Date		Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		Overfill Test Date				ATG Type					
Tank Code	08	Tank Age	32	Tank Installed Date	01/01/1990	Tank Material	Steel Clad	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	Positive Shutoff
Tag Number	1915	Spill Test Date		Piping Installed Date		Tank Construction	Double-Walled	Piping Construction	None	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Not Required	Piping Type	U.S. Suction	CP Met Types	Non-corrodible
Product	Oil, Waste	PLLD Test Date		Tank/Piping CP Test Date	01/05/2011	Primary Tank Leak Detection	Manual Interstitial Monitoring	Primary Pipe Detection	3-Year Line Tightness Test	Vapor Recovery	No
Capacity	1002	ATG Test Date		Line Tightness Test Date	11/21/2019	Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		Overfill Test Date				ATG Type					

Facility Summary in Sheridan County in the City of Plentywood

Location: SHERIDAN MEMORIAL HOSPITAL
440 W Laurel Ave
Plentywood, MT 59254-1526 Sheridan

System Facility ID:46-00795

Facility Code: 27939
Last Inspected On: 03/08/2022
Operating Permit Renewal Date: 06/03/2025

Note: Inspection is due 90 days before the Operating Permit Renewal Date.

Owner Operator Contact:	Sheridan Memorial Hospital
Operator Contact:	Mark Brensdal;Murvin Anderson4067652646;4067653700

Owner/Operator: Sheridan Memorial Hospital

Athena Gardenier, UST Class B Global Operator
Athena Gardenier, UST Class B Operator
Mark Brensdal, UST Class A Operator
Martin Carlson, UST Class B Global Operator
Murvin Anderson, UST Class A Operator

Tank Code	S3	Tank Age	24	Tank Installed Date	10/01/1998	Tank Material	Steel Clad	Piping Material	Flexible Plastic	Overfill Types	Flapper Valve
Tag Number	1918	Spill Test Date	03/07/2022	Piping Installed Date		Tank Construction	Double-Walled	Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date	03/07/2022	Catastrophic L.D Type 3.0	Auto Dialer	Piping Type	U.S. Suction	CP Met Types	Non-corrodible
Product	Heating Oil	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection	Manual Interstitial Monitoring	Primary Pipe Detection	3-Year Line Tightness Test	Vapor Recovery	No
Capacity	8000	ATG Test Date		Line Tightness Test Date	03/08/2022	Secondary Tank Leak Detection		Secondary Pipe Detection	Continuous Interstitial Monitoring	Energy Act	No
		Overfill Test Date	04/21/2022			ATG Type	Veeder Root/				

Facility Summary in Sheridan County in the City of Plentywood

Location: WELCOME STOP PLENTYWOOD, LLC
203 Raymond Rd
Plentywood, MT 59254-1545 Sheridan

System Facility ID:46-12667

Facility Code: 28312
Last Inspected On: 08/26/2021
Operating Permit Renewal Date: 11/13/2024

Note: Inspection is due 90 days before the Operating Permit Renewal Date.

Owner Operator Contact:	John Gilligan
-------------------------	---------------

Operator Contact: John Gilligan;Lance Chandler

4067652983

Owner/Operator: John Gilligan

John Gilligan, UST Class A Operator
John Gilligan, UST Class B Global Operator
John Gilligan, UST Class B Operator
Lance Chandler, UST Class A Operator
Lance Chandler, UST Class B Operator

Tank Code	01	Tank Age	31	Tank Installed Date	07/01/1991	Tank Material	Steel Clad	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	Flapper Valve
Tag Number	2954	Spill Test Date	07/15/2021	Piping Installed Date		Tank Construction	Double-Walled	Piping Construction	None	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Not Required	Piping Type	Safe Suction	CP Met Types	Non-corrodible
Product	Gasoline	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection	Manual Interstitial Monitoring	Primary Pipe Detection		Vapor Recovery	No
Capacity	10000	ATG Test Date		Line Tightness Test Date		Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		Overfill Test Date	07/15/2021			ATG Type					
Tank Code	02	Tank Age	31	Tank Installed Date	07/01/1991	Tank Material	Steel Clad	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	Flapper Valve
Tag Number	2955	Spill Test Date	07/15/2021	Piping Installed Date		Tank Construction	Double-Walled	Piping Construction	None	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Not Required	Piping Type	Safe Suction	CP Met Types	Non-corrodible
Product	Diesel	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection	Manual Interstitial Monitoring	Primary Pipe Detection		Vapor Recovery	No
Capacity	10000	ATG Test Date		Line Tightness Test Date		Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		Overfill Test Date	07/15/2021			ATG Type					

Facility Summary in Sheridan County in the City of Reserve

Location: J AND R SERVICE
101 Main St
Reserve, MT 59258 Sheridan

Facility Code: 28008
Last Inspected On: 06/28/2022
System Facility ID:46-02103
Operating Permit Renewal Date: 08/10/2025

Note: Inspection is due 90 days before the Operating Permit Renewal Date.

Owner Operator Contact: J and R Services

4062865276

Operator Contact: Jeff Brensdal

4062865276

Owner/Operator: J and R Services

Jeff Brensdal, UST Class A Operator
Jeff Brensdal, UST Class B Global Operator
Jeff Brensdal, UST Class B Operator
Ryan Brensdal, UST Class B Operator

Tank Code	05	Tank Age	22	Tank Installed Date	07/27/2000	Tank Material	Steel Clad	Piping Material	Flexible Plastic	Overfill Types	Flapper Valve
Tag Number	4213	Spill Test Date	06/28/2022	Piping Installed Date		Tank Construction	Double-Walled	Piping Construction	None	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Not Required	Piping Type	Safe Suction	CP Met Types	Non-corrodible
Product	Diesel	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection	Manual Interstitial Monitoring	Primary Pipe Detection		Vapor Recovery	No
Capacity	2000	ATG Test Date		Line Tightness Test Date		Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		Overfill Test Date	06/28/2022			ATG Type					
Tank Code	03	Tank Age	31	Tank Installed Date	05/21/1991	Tank Material	Steel Clad	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	Flapper Valve
Tag Number	4733	Spill Test Date	06/28/2022	Piping Installed Date		Tank Construction	Double-Walled	Piping Construction	None	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Not Required	Piping Type	Safe Suction	CP Met Types	Non-corrodible
Product	Gasoline	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection	Manual Interstitial Monitoring	Primary Pipe Detection		Vapor Recovery	No
Capacity	2000	ATG Test Date		Line Tightness Test Date		Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		Overfill Test Date	06/28/2022			ATG Type					